This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




FIG. 1




FIG. 2




FIG. 3





FIG. 4

5 - 16







FIG. 5A

FIG. 5B






FIG. 5C

FIG. 5D

U. Balachandran et al. - Docket No. ANL 287 METHOD FOR FABRICATION OF HIGH TEMPERATURE SUPERCONDUCTORS Harry M. Levy, Esq. (312) 663-9800




FIG. 6A




FIG. 6B

7-16




FIG. 7A




FIG. 7B




FIG. 8A




FIG. 8B




FIG. 9




FIG. 10

10-16




FIG. 11A




FIG. 11B




FIG. 11C




FIG. 12A




FIG. 12B




FIG. 13A




FIG. 13B




FIG. 14A




FIG. 14C




FIG. 14B




FIG. 14D

14-16




FIG. 15




FIG. 16A




FIG. 16B




FIG. 17